

High conversion ratio 0.76
High reliability

High conversion ratio
Traced to Fraunhofer

High conversion ratio
Traced to Fraunhofer

-
-
-

- Strict incoming material, delivery and package inspection
- Accuracy of efficiency test is controlled within $\pm 0.1\%$
- 100% Full inspection of reverse leakage and cell appearance
- Calibration piece traced to Fraunhofer

